

ਦਫਤਰ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੇ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸਾਖਾ, ਸਾਹਮਣੇ ਪੁਲਿਸ
ਸਟੇਸ਼ਨ, ਇੰਡਸਟ੍ਰੀਅਲ ਏਰੀਆ ਫੇਸ-1, ਸਹਿਬਜ਼ਾਦਾ ਅਜੀਤ ਸਿੰਘ ਨਗਰ (ਮੋਹਾਲੀ)

ਟੈਲੀਫੋਨ ਨੰ : 0172-2226328

Email id: pwdmohali@gmail.com & ee.pd.moh.pwd@punjab.gov.in

ਸੇਵਾ ਵਿਖੇ

ਵਧੀਕ ਡਿਪਟੀ ਕਮਿਸ਼ਨਰ (ਜਨਰਲ),
ਸਾਖਾ-ਐੱਲ.ਜੀ., ਕਰਮਾ ਨੰ. 309, ਦੂਜੀ ਮੰਜਿਲ,
ਮਿੰਨੀ ਸਕੱਤਰੇਤ, ਰੂਪਨਗਰ।

ਨੰ 5648

ਮਿਤੀ 16-6-23

ਵਿਸ਼ਾ: ਡੇ-ਨੂਲਮ ਸਕੀਮ ਦੇ ਸ਼ੈਲਟਰ ਫਾਰ ਅਰਬਨ ਹੋਮਲੈਸ ਕੰਪੇਨੈਂਟ ਰਾਜ ਵਿੱਚ ਬਣੇ-ਨੂਲਮ ਅਤੇ
ਨਾਨ-ਨੂਲਮ ਸੈਕਟਰਾਂ ਦਾ ਸੇਸ਼ਲ ਆਡਿਟ ਅਤੇ ਤੀਜੀ ਧਿਰਾਂ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ
ਕਰਵਾਉਣ ਸਬੰਧੀ।

ਹਵਾਲਾ: ਆਪ ਦਾ ਪੱਤਰ ਨੰ: ਏ.ਡੀ.ਸੀ(ਜ)/ਸਾਖਾ-ਐੱਲ.ਜੀ/2023/2057-2059 ਮਿਤੀ
30.05.2023

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲੇ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਡੇ-ਨੂਲਮ ਸਕੀਮ ਦੇ ਸ਼ੈਲਟਰ ਫਾਰ
ਅਰਬਨ ਹੋਮਲੈਸ ਕੰਪੇਨੈਂਟ ਰਾਜ ਵਿੱਚ ਬਣੇ-ਨੂਲਮ ਅਤੇ ਨਾਨ-ਨੂਲਮ ਸੈਕਟਰਾਂ ਅਧੀਨ ਨਗਰ ਕੌਂਸਲ ਸ਼੍ਰੀ
ਚਮਕੌਰ ਸਾਹਿਬ ਅਧੀਨ ਬਣੇ ਸ਼ੈਲਟਰ ਫਾਰ ਅਰਬਨ ਹੋਮਲੈਸ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ ਕਰਕੇ ਲੋੜੀਂਦੀ ਰਿਪੋਰਟ
ਨੱਥੀ ਪ੍ਰਫਾਰਮੇ ਤੇ ਭੇਜੀ ਜਾਂਦੀ ਹੈ।

ਨੱਥੀ/ਉਕਤ ਅਨੁਸਾਰ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੇ ਨਿ ਵਿ ਭ ਤੇ ਮ ਸਾਖਾ,
ਐਸ. ਏ. ਐਸ. ਨਗਰ।

ਪਿੱਠਅੰਕਣ ਨੰ

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ. 1, ਲੇ.ਨਿ.ਵਿ., ਭਤੇਮ
ਸਾਖਾ, ਰੂਪਨਗਰ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਲਈ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੇ ਨਿ ਵਿ ਭ ਤੇ ਮ ਸਾਖਾ,
ਐਸ. ਏ. ਐਸ. ਨਗਰ।

Performa for 3rd Party Quality Audit of Shelters for Urban Homeless

Name of ULB:	MC Shri Chaitany Sahi	Name of SUH:	Shelter for Urban Homeless
Name of Agency through which 3 rd Party Quality Audit is being conducted		Address of SUH	
Date of Audit		Capacity:	50 Beds

A) General

1	Type of Building	Residential	Commercial	Institute	Hospital	Other
		✓	—	—	—	—
2	Description	FOR HOMELESS PEOPLE				
3	Location	K-17, NEAR OLD OLD TEHSIL SH. CHANLAKAR SAHIB				
4	General information of building /structure	Approximate overall dimensions	Tehsil	Distt	length	width
			SH-CHANLAKAR SAHIB	ROHANGAR	70	42
Overall details of Building/structure						

Overall details of Building/structure		Nonsymmetrical	
No. of story	2	symmetrical	✓
No. of Rooms	2 Halls		
No. of Bathrooms	2		
No. of Kitchen	1		

B₃ RL

Starting year of construction	2018	Reference	Permission certificate	Yes
year of completion of construction	2020	Reference	completion certificate	Yes
structure is completed at one time or in stages				
Name of Architect	Gurpreet Singh	At one time	under construction	stage
Name of Engineer	A Gurpreet Singh (ANE)	address	Mo. Sagar Chawla	Contact No 98147-08526
Name of Builder	P. S. Shubhendra Singh	address	EO NC SH. CHANDRA SATHI	Contact No 9871696210
Name of contractor	The Saharan (G-4) LLC	address	Backside by Shree Naray	Contact No 98880-31088
Competent Authority	NC SH. CHANDRA SATHI	address	—	Contact No 98880-31088
Existing use	yes	Fully	partly	✓
Adjoining structure if any	✓	No		
court matter if any	yes/No	No	Report /undertaking	
security facility	yes/No	Yes/No	fencing	NOC from Fire Brigade 98
changes done in original structure/plan	yes/No			if yes, details
If minor changes done, please specify				

15	History of failure in structure or part of it, if any		NO			
16	failure of adjoining structure, if any		NO			
17	Maintenance details	structural	—			
		Non-structural	—			
		water supply /sanitary	—			
		Electrification	—			
18	Any other information like use of solar energy					
19	Inspection done in presence of					
	Name of person	address	Position	Email	contact No	
1	Sat. Vratish Jodav	DC Purbaga	DC			
2	Sh. Anvik Singh	SDM Clt	SDM			
3						
4						

B	Technical record		2018		Reference	
1	Year of construction	years	3-5			
2	Age of structure	RCC	steel grade	fe500	Steel	
3	Materials for construction	M20	steel grade	fe500	Steel	
	Grade of concrete					
					plastic/ fiber	
					Internal wall	
						Pinches

By

4

4	Documents / records available	Yes	✓	No	
	if yes, describe	plan			
		elevation			
		cross section			
		structural drawings			
		completion certificate			
		Test reports of materials			
5	Mode of construction contract	tender	✓	negotiation	—
6	Changes made in construction as compared to structural design and drawings available	—			
7	Adjoining structures available before / during construction	yes	No	—	
	if yes, details thereof	—			
8	Additional structure constructed along with this structure	yes	No	—	
9	Extension to existing structure	date		—	
	if yes, details thereof	—			
10	Delay in construction if any with reason	if yes, details thereof			
11	change of Engineer	yes	No	if yes	—

Page 10

By
F.A.

	Major repairs if any				Minor repair if any				Type of repair with reason			
	wing/flat	wing/flat	wing/flat	wing/flat	wing/flat	wing/flat	wing/flat	wing/flat	Type of repair with reason	Type of repair with reason	Type of repair with reason	Type of repair with reason
16	Any structural defects observed like				Type							
	wing/flat	wing/flat	wing/flat	wing/flat	settlement	major/minor cracks	yes/No	yes/No	Hair crack (small) observed in plaster of wall of Hall	Tilting	yes/No	
					leakage in slab		yes/No			roof slab	yes/No	
					seepage in slab		yes/No			roof slab	yes/No	
					spalling of plaster		yes/No		bottom 2' of wall of Hall	roof slab	yes/No	
					major/minor cracks in plaster				junction of two walls of Ramp	roof slab	yes/No	
17	Signs of failure at Ground Floor				No							
18	compound wall details											
19	Signs of failure in compound wall				No							

Note: 1. Railing should be provided in Ramp.
 2. Roof is not accessible. Hence pruning of trees falling above roof should be done regularly to avoid blockage of rain water pipes.

RA

Exec Director
 Provincial
 S.A.S. N

WD B&R Br.