Performa for 3rd Party Quality Audit of Shelters for Urban Homeless Name of ULB: Name of SUH: MC HASITH A
Dryphard Industrial
Training Institute
Ameritaar Name of Agency through which 3rd Sheller for wha Party Quality Audit is being conducted Address of SUH Hear He office Date of Audit 05-02-24 Capacity: A) General Residential Commercial Institute Hospital Other Type of Building Gout 2 Description Main Road, Majitha 3 ML MASITHA Location Tehsil Distt MASITH General information of building Approximate overall 4 length width height /structure 12 . dimensions 10 41 Overall details of Building/structure No. of story symmetrical Nonsymmetrical Grand 5 No. of Rooms By No. of Bathrooms 1 No. of Kitchen 0

HUNEXURE-IV

0	T								
	Starting year of construction	establish pre-buil building	ed wis	Re	ference	Permiss certifica			
	year of completion of construction	0		Re	ference	comple certific			
	structure is complete in stag		or		· .	und constru		stage	
6	Name of Architect	NA	ac	ldress		NA		Contact No	NA
7	Name of Engineer	V	ac	ldiess		<b>V</b>		Contact No	"
8	Name of Builder	4	ac	ldess		4 .	e de la companya de l	Contact No	7
9	Name of contractor	11	ac	ld ess		7		Contact No	7
10	Competent Authority		e						
1	Existing use yes	V	No		Fully	~	partly		
2	Adjoining structure i	NA	• 1					ų.	•
3	court matter if any	yes/No	i	f es,	/und	eport ertaking			8
	security facility	yes/No	fe	ning	Yes/No		NOC	om Fire Brigade	
1	changes done in or		s/ No				if yes, d	ails	
	If minor changes done, specify	plance	ρo	7	H	Metro			
					নেৱাৰ উন্ন	5 111	B.		

15	History of fa	ailure in structure or part of it, if any	- NA-	-					
6	failure of ad	joining structure, if any	No	NO					
		structural	Yes		/				
		Non-structural	No						
7	Maintenance details	water supply /sanitary	Ves	Ves					
		Electrification	Yes						
8	Any other infor	mation like use of solar ene	rgy NO						
9	Inspe	ction done in presence of			•				
		- Name of person	address	Position	- Email	contact No			
	1				10-12 E <sub>1</sub>				
	2				,	de la decima decima de la decima decima de la decima de l			
	. 3		•						
	4								

1	Year of construction		2010	- 1	R	eference			
2	Age of structure	years	. 14						
3	Materials for construction Grade of concrete	RCC	steel grade	Steel	wall Tk	Masc External wall	onry 🗸	plastic/ fiber Internal wall	
							B-A		ਧਕ ਅਫਸਰ ਸਲ ਮਜੀਠਾ

4	Documents / records available					
( )		Yes	Mo	-20		
	if yes, describe	plan				
$\vdash$		elevation				-
L		cross section				
		structural drawings			,	
		completion ce	rtificate		-	
		Test reports materials				
	S . S . S . L . L	any other doc	cument			
5	Mode of construction contract	tender	negot	tiation	If any other, please specify	· -
6	Changes made in cons	truction as compared	to structur	ral design and dra	awings available	NA
7	Adjoining structures available be		1	res/No		
	•	letails thereof		* P		
8	Additional structure constructed	d alongwith this struc	ture y	ves/No		
	•					
9	Extension to existi	ngstructure		date		
Í	if yes, details					+
10	Delay in construction if any wit			o if yes,	details thereof	
11		yes/No.	jfy	yes		
44			ੇ ਕਾਰ ਨਰ	ਰਜ ਸਾਧਕ ਅਫਸੰਵ ਗੁਰੂ ਕੋਂਸਲ ਮੁਜੀਨਾ	By	

+					details	100				
change of contractor		yes/No. NA		if yes						
2	stages of construction		•	,	details					
$\top$										
3	Maintenance Type	water proofing		yes/No	yes/No		If yes, frequency		yrs/month	
		pl	plastering		i lago		If yes, frequency		yrs/month	
			coloring	yes/No			yes, uency	374	yrs/month	
		st	rengthenin g	yes/No			yes, uency		yrs/month	-
			water supply			÷				
			drainage	y¢s/No	, a = 1		yes, quency	Quarte	grs/month	
14	Previous inspection	s done	yés/No							
	if yes, details	· . * 6/*		in the second			reason	Forma	l inspect	tion
	document available	;	yes/No.					y.		
	If, done when	•			ne of nority	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
15	Action taken then, yes/	No			f yes, letails			<b>A</b> ,	01	
	d a			Principa Dayana Amritsa	nd Indust	trial Training I	astitute	ਕਾਰ <b>ਿ</b> ਨਗਰ	ਮਾਹਕ ਅਫਸਰ ਕੇਂਸਲ ਮਜੀਨਾ	

	J1										
	Major repairs if any	airs if any NA		Type of repair with reason							
	Minor repair if any	NA		Ty	pe of repa reason		7. 2				
16	Any structural d	efects observed like			Type		Tilting	ves/No			
	wing/flat wing/flat	wing/flat wing/flat	settlement		yes/No		Tilling	yc3/110			
	wing nad wing nad prompt to		major/ m		yes/No			* 1		, .	
			leakage	11	yes/No		roof slab	yes/No			
			seepage	in slab	yes/No		roof slab	yes/No	,		
		· · · · · · · · · · · · · · · · · · ·		lling of laster	yes/No		roof slab	yes/No			-
	m	ajor/minor cracks in			yes/No		roof slab	yes/No			
L											
1	7 Signs of failure	at Ground Floor				y Project		, , , , , , , , , , , , , , , , , , , ,	•		
Ī	18 compoun	d wall details	والمرشور والمراجع								41.1
	19 Signs of failure in	n compound wall		THE STATE		3	Ba		44 14		