



ਦਫਤਰ - ਵਧੀਕ ਡਿਪਟੀ ਕਮਿਸ਼ਨਰ (ਜਨਰਲ), ਰੂਪਨਗਰ
ਕਮਰਾ ਨੰ.309, ਦੂਜੀ ਮੰਜਿਲ, ਮਿੰਨੀ ਸਕੱਤਰੇਤ, ਰੂਪਨਗਰ

ਈਮੇਲ: adcg.lg@punjab.gov.in

ਸੇਵਾ ਵਿਖੇ,

ਸੰਸ਼ੁਕਤ ਡਾਇਰੈਕਟਰ,
ਡਾਇਰੈਕਟੋਰੇਟ ਸਥਾਨਕ ਸਰਕਾਰ ਵਿਭਾਗ ਪੰਜਾਬ,
ਚੰਡੀਗੜ੍ਹ।

ਪੱਤਰ ਨੰ: ਏ.ਡੀ.ਸੀ.(ਜ)ਐੱਲ.ਜੀ.ਸਾਖਾ-2023/2503

ਮਿਤੀ: 04/7/23

ਵਿਸ਼ਾ:- ਡੇ-ਨੂਲਮ ਸਕੀਮ ਦੇ ਸ਼ੈਲਟਰ ਫਾਰ ਅਰਬਨ ਹੋਮਲੈਸ ਕੰਪੇਨੈਂਟ ਅਧੀਨ ਰਾਜ ਵਿੱਚ ਬਣੇ ਨੂਲਮ ਅਤੇ ਨਾਨ-ਨੂਲਮ ਸ਼ੈਲਟਰਾਂ ਦਾ ਸੋਸ਼ਲ ਆਡਿਟ ਅਤੇ ਤੀਜੀ ਧਿਰ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ ਕਰਵਾਉਣ ਸਬੰਧੀ।

ਹਵਾਲਾ:- ਆਪ ਦੇ ਪੱਤਰ ਨੰ. ਪਸੂਲਮ/SJH/57/2022-562 ਮਿਤੀ 17.05.2023 ਸਬੰਧੀ।

ਉਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਆਪ ਵੱਲੋਂ ਨੂਲਮ ਅਤੇ ਨਾਨ-ਨੂਲਮ ਸ਼ੈਲਟਰਾਂ ਦਾ ਸੋਸ਼ਲ ਆਡਿਟ ਅਤੇ ਤੀਜੀ ਧਿਰ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ ਕਰਵਾਉਣ ਉਪਰੰਤ ਰਿਪੋਰਟ ਭੇਜਣ ਲਈ ਲਿਖਿਆ ਗਿਆ ਸੀ। ਜਿਸ ਸਬੰਧੀ ਜ਼ਿਲ੍ਹੇ ਵਿੱਚ ਪੈਦੀਆਂ ਨਗਰ ਕੌਂਸਲਾਂ/ਨਗਰ ਪੰਚਾਇਤਾਂ, ਦਾ ਆਡਿਟ ਹੇਠ ਲਿਖੇ ਅਨੁਸਾਰ ਏਜੰਸੀਆਂ ਪਾਸੋਂ ਮੁਕੰਮਲ ਕਰਵਾ ਲਿਆ ਗਿਆ ਹੈ:-

ਨਗਰ ਕੌਂਸਲ/ਨਗਰ ਪੰਚਾਇਤ ਦਾ ਨਾਮ	ਆਡਿਟ ਕਰਨ ਲਈ ਸਬੰਧਤ ਏਜੰਸੀ ਦਾ ਨਾਮ
1. ਨਗਰ ਕੌਂਸਲ, ਰੂਪਨਗਰ	ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪੀ.ਡਬਲਿਊ.ਡੀ. ਉਸਾਰੀ ਮੰਡਲ, ਰੂਪਨਗਰ।
2. ਨਗਰ ਕੌਂਸਲ, ਨੰਗਲ	
3. ਨਗਰ ਕੌਂਸਲ, ਸ਼੍ਰੀ ਅਨੰਦਪੁਰ ਸਾਹਿਬ	
4. ਨਗਰ ਪੰਚਾਇਤ, ਕੀਰਤਪੁਰ ਸਾਹਿਬ	
5. ਨਗਰ ਕੌਂਸਲ, ਮੋਰਿੰਡਾ	ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪੀ.ਡਬਲਿਊ.ਡੀ. ਉਸਾਰੀ ਮੰਡਲ, ਮੋਹਾਲੀ
6. ਨਗਰ ਕੌਂਸਲ, ਸ਼੍ਰੀ ਚਮਕੌਰ ਸਾਹਿਬ	ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪੀ.ਡਬਲਿਊ.ਡੀ. ਉਸਾਰੀ ਮੰਡਲ, ਸ਼੍ਰੀ ਚਮਕੌਰ ਸਾਹਿਬ।

ਉਕਤ ਸਬੰਧੀ ਏਜੰਸੀਆਂ ਪਾਸੋਂ ਪ੍ਰਾਪਤ ਰਿਪੋਰਟ ਆਪ ਨੂੰ ਨਾਲ ਨੱਥੀ ਕਰਕੇ ਸੂਚਨਾ ਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜੀ ਜਾਂਦੀ ਹੈ ਜੀ।

ਨੱਥੀ:- ਉਕਤ ਅਨੁਸਾਰ।

ਵਧੀਕ ਡਿਪਟੀ ਕਮਿਸ਼ਨਰ (ਜ)
ਰੂਪਨਗਰ।

ਦਫਤਰ: ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ, ਰੂਪਨਗਰ
ਈ-ਮੇਲ:- pwdropar@yahoo.co.in ਫੋਨ ਨੰ: 01881-222934

ਵੱਲ

ਵਧੀਕ ਡਿਪਟੀ ਕਮਿਸ਼ਨਰ, (ਜਨਰਲ),

ਰੂਪਨਗਰ।

ਪੱਤਰ ਨੰਬਰ:- 6964

ਮਿਤੀ:- 19-6-2023

ਵਿਸ਼ਾ:-


ਡੇ-ਨੂਲਮ ਸਕੀਮ ਦੇ ਸੈਲਟਰ ਫਾਰ ਅਰਬਨ ਹੋਮਲੈਸ ਕੰਪੋਨੈਂਟ ਰਾਜ ਵਿੱਚ ਬਣ-ਨੂਲਮ ਅਤੇ ਨਾਨ ਨੂਲਮ ਸੈਲਟਰਾਂ ਦਾ ਸੋਸਲ ਆਡਿਟ ਅਤੇ ਤੀਜੀ ਧਿਰਾਂ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ ਕਰਵਾਉਣ ਸਬੰਧੀ।

ਹਵਾਲਾ:-

ਆਪ ਜੀ ਦਾ ਨੰਬਰ ਏ.ਡੀ.ਸੀ(ਜ)/ਸਾਖਾ/2023/2057-2059 ਮਿਤੀ 30-05-2023

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲੇ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਜੀ ਨੂੰ ਬੇਨਤੀ ਸਹਿਤ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਮੰਡਲ ਦੇ ਸਬੰਧਤ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਅਤੇ ਸਬੰਧਤ ਈ.ਓ ਦੀ ਹਾਜ਼ਰੀ ਵਿੱਚ ਨਗਰ ਕੌਂਸਲ, ਰੂਪਨਗਰ, ਨਗਰ ਕੌਂਸਲ, ਨਗਲ ਅਤੇ ਨਗਰ ਕੌਂਸਲ ਸ੍ਰੀ ਅਨੰਦਪੁਰ ਸਾਹਿਬ ਅਤੇ ਕੀਰਤਪੁਰ ਸਾਹਿਬ ਵਿਖੇ ਡੇ-ਨੂਲਮ ਸਕੀਮ ਦੇ ਸੈਲਟਰ ਫਾਰ ਅਰਬਨ ਹੋਮਲੈਸ ਕੰਪੋਨੈਂਟ ਰਾਜ ਵਿੱਚ ਬਣ-ਨੂਲਮ ਅਤੇ ਨਾਨ ਨੂਲਮ ਸੈਲਟਰਾਂ ਦਾ ਸੋਸਲ ਆਡਿਟ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਨਿਰਧਾਰਤ ਪ੍ਰਫਾਰਮਿਸ਼ਾਂ ਤੇ ਤਿਆਰ ਕਰਕੇ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਲਈ ਭੇਜੀ ਜਾਂਦੀ ਹੈ ਜੀ।

ਨੱਥੀ/ਉਕਤ ਅਨੁਸਾਰ।



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ


ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ,

ਰੂਪਨਗਰ।

ਮਿਤੀ :-

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ :-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਰੂਪਨਗਰ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ 1102 ਮਿਤੀ 15-06-2023 ਅਤੇ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਪ੍ਰਾਂਤਕ / ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਸ੍ਰੀ ਅਨੰਦਪੁਰ ਸਾਹਿਬ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਕਰਮਵਾਰ ਪੱਤਰ ਨੰਬਰ 827 ਮਿਤੀ 19-06-2023 ਅਤੇ 515 ਮਿਤੀ 16-06-2023 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾਂ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ

ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ,

ਰੂਪਨਗਰ।

Performa for 3rd Party Quality Audit of Shelters for Urban Homeless

Name of ULB:	M.C. Nangal	Name of SUH:	MC Night Shelters
Name of Agency through which 3 rd Party Quality Audit is being conducted	P.W.D	Address of SUH	Near Shingar Beauti parlar Adda Markeet Nangal Town/Ship
Date of Audit	14/06/2023	Capacity:	15-BEO

A) General						
1	Type of Building	Residential	Commercial	Institute	Hospital	Other
						✓
2	Description	Urban Homeless Shelters				
3	Location	Near Shingar Beauti parlar Adda Markeet Nangal.				
4	General information of building /structure	Approximate overall dimensions	Tehsil	Nangal	length	width
Overall details of Building/structure						
5	No. of story		✓	symmetrical		Nonsymmetrical
	No. of Rooms			01	B3	
	No. of Bathrooms			01		
	No. of Kitchen			01		

B₃

Starting year of construction		2017		Reference		Permission certificate			
year of completion of construction		2018		Reference		completion certificate			
structure is completed at one time or in stages				Single stage		under construction		stage	
								Single	
6	Name of Architect		address			Contact No			
7	Name of Engineer	Mukesh M.E.	address			Contact No			
8	Name of Builder	Suresh Maik	address	The Ropar Adresh Cop Socity		Contact No		94170-21357	
9	Name of contractor	Suresh Malik	address	H. No:- 6/Railway Road Nangal T/Ship		Contact No		94170-21357	
10	Competent Authority								
11	Existing use	yes ✓	No	Fully ✓		partly			
12	Adjoining structure if any		- NA -						
13	court matter if any	yes/No ✓	if yes,	Report /undertaking		- NA -			
security facility		yes/No ✓	fencing	Yes/No ✓		NOC from Fire Brigade		Yes	
14	changes done in original structure/plan		yes/ No ✓	if yes, details					
If minor changes done, please specify			- NO -						

22

15	History of failure in structure or part of it, if any		- NA -		
16	failure of adjoining structure, if any		- NA -		
17	Maintenance details	structural	- NO -		
		Non-structural	- NO -		
		water supply /sanitary	- NO -		
		Electrification	- NO -		
18	Any other information like use of solar energy		- NO -		
19	Inspection done in presence of		Mukesh Sharma		
	Name of person	address	Position	Email	contact No
1	Kuldeep Agarwal				96463-00679
2	Mukesh Sharma				96463-00484
3	Malkeet Singh				
4	Jaswinder Kaur				96463-92133

B		Technical record		Reference	
1	Year of construction	2017			
2	Age of structure	years	5 YEARS		
3	Materials for construction	RCC		Steel	
	Grade of concrete	M-20	steel grade	wall Tk	External wall
				Masonry	Brick work
				plastic/ fiber	Internal wall
					- NA -

24/11/20

4	Documents / records available		Yes	No		
	if yes,	describe	plan			
			elevation			
			cross section			
			structural drawings			
			completion certificate			
			Test reports of materials			
			any other document			
5	Mode of construction contract		tender		negotiation	If any other, please specify
6	Changes made in construction as compared to structural design and drawings available					
7	Adjoining structures available before / during construction			yes/No		- Nil -
	if yes, details thereof					
8	Additional structure constructed along with this structure			yes/No		
9	Extension to existing structure			date	- Nil -	
	if yes, details thereof					
10	Delay in construction if any with reason		No Delay		if yes, details thereof	
11	change of Engineer	yes/No		if yes		

Red

	Major repairs if any	- Nil -	Type of repair with reason		- Nil -
	Minor repair if any	- Nil -	Type of repair with reason		- Nil -
16	Any structural defects observed like	- Nil -	Type		- Nil -
	wing/flat	wing/flat	settlement	yes/No	Tilting yes/No
			major/ minor cracks	yes/No	
			leakage in slab	yes/No	roof slab yes/No
			seepage in slab	yes/No	roof slab yes/No
			spalling of plaster	yes/No	roof slab yes/No
	major/minor cracks in plaster			yes/No	roof slab yes/No
17	Signs of failure at Ground Floor		- Nil -		
18	compound wall details		- Nil -		
19	Signs of failure in compound wall		- Nil -		

Bay

Sub Divisional Engineer
Const. Sub Division
PWD B&R Sri Anandpur Sahib