



ਦਫਤਰ ਨਗਰ ਕੌਂਸਲ ਉੜਮੁੜ ਟਾਂਡਾ
Office of the Municipal Council
Urmar Tanda (Distt Hoshiarpur)



ਨੰਬਰ:
ਮਿਤੀ:

 mc_urmartanda@yahoo.co.in
 01886-222043

ਸੇਵਾ ਵਿਖੇ,

ਟੈਕਨੀਕਲ ਡਾਇਰੈਕਟਰ,
ਸਥਾਨਕ ਸਰਕਾਰ ਵਿਭਾਗ, ਪੰਜਾਬ,
ਪੰਜਾਬ ਸਟੇਟ ਅਰਬਨ ਲਾਈਵਲੀਹੁਡ ਮਿਸ਼ਨ,
ਮਿਊਂਸਪਲ ਭਵਨ, ਪਲਾਟ ਨੰ:3,
ਸੈਕਟਰ 35-ਏ, ਚੰਡੀਗੜ੍ਹ।

ਵਿਸ਼ਾ:- ਡੇ-ਨੂਲਮ ਸਕੀਮ ਦੇ ਸ਼ੈਲਟਰ ਫਾਰ ਅਰਬਨ ਹੋਮਲੈਸ ਕੰਪੋਨੈਂਟ ਅਧੀਨ ਰਾਜ ਵਿੱਚ ਬਣੇ ਨੂਲਮ ਅਤੇ ਨਾਨ-ਨੂਲਮ ਸ਼ੈਲਟਰਾਂ ਦਾ ਸ਼ੋਸ਼ਲ ਆਡਿਟ ਅਤੇ ਤੀਜੀ ਪਿਰ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ ਕਰਵਾਉਣ ਸਬੰਧੀ।

ਹਵਾਲਾ:- ਆਪ ਜੀ ਦੇ ਦਫਤਰ ਦੇ ਪੱਤਰ ਨੰ: PSULM/SUH-57/2023/1909 ਮਿਤੀ: 22/12/2023 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਤੇ ਹਵਾਲੇ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਬੇਨਤੀ ਕੀਤੀ ਜਾਂਦੀ ਹੈ ਕਿ ਨਗਰ ਕੌਂਸਲ, ਉੜਮੁੜ ਟਾਂਡਾ ਨਾਨ-ਨੂਲਮ ਨਾਈਟ ਸ਼ੈਲਟਰ ਦਾ ਗੁਰੂ ਨਾਨਕ ਅਈ.ਟੀ.ਆਈ.ਦਸੂਹਾ ਰਾਂਗੀਂ ਤੀਜੀ ਪਿਰ ਦਾ ਕੁਆਲਿਟੀ ਆਡਿਟ ਕਰਵਾ ਦਿੱਤਾ ਗਿਆ ਹੈ ਜੋ ਕਿ ਅਨੈਕਚਰ-4 ਨਾਲ ਨੱਥੀ ਕਰਕੇ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾ ਰਿਹਾ ਹੈ ਜੀ।

ਨੀ/-
ਕਾਰਜ ਸਾਧਕ ਅਫਸਰ,
ਨਗਰ ਕੌਂਸਲ, ਉੜਮੁੜ ਟਾਂਡਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ: 377 ਮਿਤੀ: 28/3/2024
ਉਪਰੋਕਤ ਦਾ ਇਸ ਦਾ ਇੱਕ ਉਤਾਰਾ ਵਧੀਕ ਡਿਪਟੀ ਕਮਿਸ਼ਨਰ ਹੁਸ਼ਿਆਰਪੁਰ (ਜ) ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


ਕਾਰਜ ਸਾਧਕ ਅਫਸਰ,
ਨਗਰ ਕੌਂਸਲ, ਉੜਮੁੜ ਟਾਂਡਾ।

Performa for 3rd Party Quality Audit of Shelters for Urban Homeless

Name of ULB:	URMARTANDA	Name of SUH:	Near Bus stand Tunda
Name of Agency through which 3 rd Party Quality Audit is being conducted	Gyanvansh FTI Durgam	Address of SUH	M.C. Office Urmartanda
Date of Audit	18.3.24	Capacity:	2 Beds

A) General									
1	Type of Building	Residential	Commercial	Institute	Hospital	Other			
2	Description								
3	Location	Ward No. 8 near Bus stand Tunda							
4	General information of building /structure	Approximate overall dimensions		length	15 FT	width	10 FT	height	10 FT
Overall details of Building/structure									
No. of story		1		symmetrical		Nonsymmetrical		✓	
No. of Rooms		1							
No. of Bathrooms		1							
No. of Kitchen		1							

3

	Starting year of Construction		2016		Reference		Permission certificate			
	year of completion of construction		2016		Reference		completion certificate			
structure is completed at one time or in stages			Completed		under construction		stage			
6	Name of Architect	Pawandubh Construction copy		address		Kashi Mohan Lal Sharma Tola		Contact No		98551-33315
7	Name of Engineer	—		address		—		Contact No		—
8	Name of Builder	—		address		—		Contact No		—
9	Name of contractor			address		—		Contact No		—
10	Competent Authority									
11	Existing use	yes	Yes	No	Fully	Fully	partly			
12	Adjoining structure if any									
13	court matter if any	yes/No	Yes/No	No	if yes, Report /undertaking	Yes/No	NOC from Fire Brigade			
security facility		yes/No			fencing	Yes/No	if yes, details			
14	changes done in original structure/plan		yes/No	yes/No	No					
If minor changes done, please specify		No -								

By

15	History of failure in structure or part of it, if any		No -		
16	failure of adjoining structure, if any		No -		
17	Maintenance details	structural	Structure		
		Non-structural			
		water supply /sanitary	Yes		
		Electrification	Yes		
18	Any other information like use of solar energy				
19	Inspection done in presence of				
	Name of person	address	Position	Email	contact No
1	Ajay Seini	m.c. office	SI	lo mctoda@gmail.com	
2	Akashdeep Marwaha	Tanola	Clerk		
3					
4					

B	Technical record					
1	Year of construction	years	Reference			
2	Age of structure					
3	Materials for construction	RCC	Steel	Maasonry	plastic/ fiber	
	Grade of concrete	—	steel grade	External wall	Internal wall	

Ref

4	Documents / records available	Yes	Yes	No	Record are available m.c names - <u>yes</u>			
	if yes, describe	plan	elevation					
		cross section						
		structural drawings						
		completion certificate						
		Test reports of materials						
		any other document						
5	Mode of construction contract	tender		negotiation		If any other, please specify		
6	Changes made in construction as compared to structural design and drawings available							
7	Adjoining structures available before / during construction	yes/No						
	if yes, details thereof							
8	Additional structure constructed along with this structure	yes/No						
9	Extension to existing structure	date						
	if yes, details thereof							
10	Delay in construction if any with reason					if yes, details thereof		
11	change of Engineer	yes/No.		if yes				

Ref

				details			
12	change of contractor	yes/No.	No	if yes, details	—		
12	stages of construction						

13	Maintenance Type	water proofing	yes/No	No	If yes, frequency		yrs/month		
		plastering	yes/No	No	If yes, frequency		yrs/month		
		coloring	yes/No	Yes	If yes, frequency		yrs/month	1 year.	
		strengthening	yes/No	No	If yes, frequency		yrs/month		
		water supply		Yes					
14	Previous inspections done if yes, details document available	drainage	yes/No	Yes	If yes, frequency		yrs/month	1 year.	
		No							
		reason							
15	Action taken then, yes/ No	yes/No.	No	name of authority					
		if yes, details							

12/11/20

	Major repairs if any			Type of repair with reason	
	Minor repair if any			Type of repair with reason	
16	Any structural defects observed like			Type	
	wing/flat	wing/flat	wing/flat	wing/flat	
	settlement			yes/No	
	major/ minor cracks			yes/No	
	leakage in slab			yes/No	No
	seepage in slab			yes/No	No
	spalling of plaster			yes/No	No
	major/minor cracks in plaster			yes/No	No
17	Signs of failure at Ground Floor		No		
18	compound wall details		Compound walls are intact		
19	Signs of failure in compound wall		No (No sign detected for failure)		

Boys

Principal
Guru Nanak I.T.I.
Dastiy (Hoshiarpur)